

**Flood Control Project Maintenance
Levee Inspections
LMA District Cover Sheet
Spring 2012 Levee Inspection Results**

Lake County Watershed Protection District

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

* SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2012 Levee Inspection Results

Lake County Watershed Protection District

Waterway		Bank	Unit Miles
Unit No. 01 Middle Creek		Left	3.42

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/11/2012 - 4/11/2012			
DWR Inspector	Bob Duffey			
Accompanied By	Tom Smythe Lake Co.			

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Lake County Watershed Protection District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Middle Creek	Left	3.42	04/11/2012 04/11/2012	Bob Duffey

LMIR No.	Levee Mile		Category	Item	* Location	+ Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1			Earthen Levee	Operations & Maintenance Manuals	LS	A Ma		°	°	10
DWR ID: DWR_NA0009_01_s_2012_10										
2			Earthen Levee	Emergency Supplies & Equipment	LS	A Ma		°	°	11
DWR ID: DWR_NA0009_01_s_2012_11										
3			Earthen Levee	Flood Preparedness & Training	LS	A Ma		°	°	12
DWR ID: DWR_NA0009_01_s_2012_12										
4	0.54	0.54	Earthen Levee	Vegetation	LS	A Ma	V1 : Control annual grass and weeds on the levee slopes and easements.	39.183817 ° -122.911285 °	39.183817 ° -122.911285 °	9 Y
DWR ID: DWR_NA0009_01_s_2012_9										
5	2.10	2.10	Earthen Levee	Encroachments	CR	C Ma	PI : Pipe	39.162317 ° -122.915502 °	39.162317 ° -122.915502 °	1
DWR ID: DWR_NA0009_01_s_2012_1										
6	2.40	2.40	Earthen Levee	Encroachments	LS	M En	BU : Buildings	39.160217 ° -122.912957 °	39.161692 ° -122.911748 °	7
DWR ID: DWR_NA0009_01_s_2012_7										
7	2.48	2.55	Earthen Levee	Vegetation	LS	M Ma	V2 : Remove the wild growth other than native grasses from the levee slopes.	39.161615 ° -122.911733 °	39.160795 ° -122.912442 °	3
DWR ID: DWR_NA0009_01_s_2012_3										
8	2.58	2.61	Earthen Levee	Encroachments	LS	M En	FE : Fences	39.160398 ° -122.912837 °	39.159952 ° -122.913220 °	4 Y
DWR ID: DWR_NA0009_01_s_2012_4										
9	2.62	2.67	Earthen Levee	Vegetation	LS	M En	V6 : Landscaping	39.159657 ° -122.913345 °	39.159657 ° -122.913345 °	5
DWR ID: DWR_NA0009_01_s_2012_5										
10	2.68	2.73	Earthen Levee	Vegetation	LS	M Ma	V2 : Remove the wild growth other than native grasses from the levee slopes.	39.159117 ° -122.913442 °	39.158408 ° -122.913557 °	6
DWR ID: DWR_NA0009_01_s_2012_6										

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Lake County Watershed Protection District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Middle Creek	Left	3.42	04/11/2012 04/11/2012	Bob Duffey

Levee Mile Report Line	4
Start Levee Mile	0.54
End Levee Mile	0.54
Location	Land Side
Category	Earthen Levee
Item	Vegetation
View of the levee with no vegetation on either slope.	
rduffey_s_20120416_591.jpg	



Levee Mile Report Line	8
Start Levee Mile	2.58
End Levee Mile	2.61
Location	Land Side
Category	Earthen Levee
Item	Encroachments
View of the fences at the L/S toe.	
rduffey_s_20120312_358.jpg	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2012 Levee Inspection Results

Lake County Watershed Protection District

Waterway	Bank	Unit Miles
Unit No. 02 Middle Creek	Right	3.13

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/11/2012 - 4/11/2012			
DWR Inspector	Bob Duffey			
Accompanied By	Tom Smythe Lake Co.			

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Lake County Watershed Protection District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Middle Creek	Right	3.13	04/11/2012 04/11/2012	Bob Duffey

LMR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	3.10	Earthen Levee	Vegetation	WS	A Ma	V1 : Control annual grass and weeds on the levee slopes and easements.	39.189726 ° -122.908022 °	39.148683 ° -122.913513 °	6
DWR ID: DWR_NA0009_02_s_2012_6										
2	0.00	3.10	Earthen Levee	Vegetation	LS	A Ma	V1 : Control annual grass and weeds on the levee slopes and easements.	39.189739 ° -122.908059 °	39.148683 ° -122.913513 °	4
DWR ID: DWR_NA0009_02_s_2012_4										
3	0.20	0.20	Earthen Levee	Encroachments	LS	U En	BU : Buildings	39.187039 ° -122.908880 °	39.187039 ° -122.908880 °	1 Y
DWR ID: DWR_NA0009_02_s_2012_1										
4	0.39	0.39	Earthen Levee	Slope Stability	LS	M Ma	S1 : Repair slope instability.	39.185160 ° -122.911138 °	39.185160 ° -122.911138 °	8 Y
DWR ID: DWR_NA0009_02_s_2012_8										
5	1.03	1.04	Earthen Levee	Vegetation	LS	M Ma	V2 : Remove the wild growth other than native grasses from the levee slopes.	39.177218 ° -122.913673 °	39.176992 ° -122.913642 °	7
DWR ID: DWR_NA0009_02_s_2012_7										
6	1.05	1.05	Earthen Levee	Encroachments	LS	M En	BU : Buildings	39.176875 ° -122.913685 °	39.176875 ° -122.913685 °	5 Y
DWR ID: DWR_NA0009_02_s_2012_5										
7	1.06	1.06	Earthen Levee	Encroachments	LS	M Ma	TR : Tree or limb	39.176835 ° -122.913558 °	39.176835 ° -122.913558 °	3 Y
DWR ID: DWR_NA0009_02_s_2012_3										
8	1.06	1.06	Earthen Levee	Encroachments	LS	U En	FE : Fences	39.176815 ° -122.913540 °	39.176815 ° -122.913540 °	2 Y
DWR ID: DWR_NA0009_02_s_2012_2										

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Lake County Watershed Protection District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Middle Creek	Right	3.13	04/11/2012 04/11/2012	Bob Duffey

Levee Mile Report Line	3
Start Levee Mile	0.20
End Levee Mile	0.20
Location	Land Side
Category	Earthen Levee
Item	Encroachments
View of the vegetation and building next to the landside toe of levee.	
rduffey_s_20120312_359.jpg	



Levee Mile Report Line	4
Start Levee Mile	0.39
End Levee Mile	0.39
Location	Land Side
Category	Earthen Levee
Item	Slope Stability
View of erosion along slope of the levee by both sides of the headwall.	
rduffey_s_20120416_592.jpg	



Levee Mile Report Line	6
Start Levee Mile	1.05
End Levee Mile	1.05
Location	Land Side
Category	Earthen Levee
Item	Encroachments
View of building & vegetation along the levee toe.	
rduffey_s_20120312_362.jpg	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Lake County Watershed Protection District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Middle Creek	Right	3.13	04/11/2012 04/11/2012	Bob Duffey

Levee Mile Report Line	7
Start Levee Mile	1.06
End Levee Mile	1.06
Location	Land Side
Category	Earthen Levee
Item	Encroachments
View of the tree prunings on the W/S toe.	
rduffey_s_20120312_361.jpg	



Levee Mile Report Line	8
Start Levee Mile	1.06
End Levee Mile	1.06
Location	Land Side
Category	Earthen Levee
Item	Encroachments
View of the building & fence along the L/S toe.	
rduffey_s_20120312_360.jpg	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2012 Levee Inspection Results

Lake County Watershed Protection District

Waterway	Bank	Unit Miles
Unit No. 03 Scotts Creek	Left	1.35

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/11/2012 - 4/11/2012			
DWR Inspector	Bob Duffey			
Accompanied By	Tom Smythe Lake Co.			

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Lake County Watershed Protection District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Scotts Creek	Left	1.35	04/11/2012 04/11/2012	Bob Duffey

LMR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.03	0.91	Earthen Levee	Vegetation	LS Ma	A	V1 : Control annual grass and weeds on the levee slopes and easements.	39.148608 ° -122.914424 °	39.159709 ° -122.920901 °	2
DWR ID: DWR_NA0009_03_s_2012_2										
2	0.03	0.91	Earthen Levee	Vegetation	WS Ma	A	V1 : Control annual grass and weeds on the levee slopes and easements.	39.148607 ° -122.914424 °	39.159709 ° -122.920901 °	3
DWR ID: DWR_NA0009_03_s_2012_3										
3	0.26	0.26	Earthen Levee	Vegetation	LS Ma	A	V1 : Control annual grass and weeds on the levee slopes and easements.	39.151282 ° -122.916770 °	39.151282 ° -122.916770 °	5 Y
DWR ID: DWR_NA0009_03_s_2012_5										
4	0.97	0.97	Earthen Levee	Encroachments	WS En	M	TA : Tank	39.160108 ° -122.922110 °	39.160108 ° -122.922110 °	1 Y
DWR ID: DWR_NA0009_03_s_2012_1										
5	1.06	1.12	Earthen Levee	Vegetation	LS Ma	M	V2 : Remove the wild growth other than native grasses from the levee slopes.	39.159772 ° -122.923540 °	39.159605 ° -122.924610 °	4
DWR ID: DWR_NA0009_03_s_2012_4										

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Lake County Watershed Protection District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Scotts Creek	Left	1.35	04/11/2012 04/11/2012	Bob Duffey

Levee Mile Report Line	3
Start Levee Mile	0.26
End Levee Mile	0.26
Location	Land Side
Category	Earthen Levee
Item	Vegetation
View of the grasses on both slopes of the levee.	
rduffey_s_20120416_593.jpg	



Levee Mile Report Line	4
Start Levee Mile	0.97
End Levee Mile	0.97
Location	Water Side
Category	Earthen Levee
Item	Encroachments
View of a tank that needs to be removed from the W/S slope.	
rduffey_s_20120312_363.jpg	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2012 Levee Inspection Results

Lake County Watershed Protection District

Waterway	Bank	Unit Miles
Unit No. 04 Poge, Alley and Clover Creek Diversion	Right	1.53

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/11/2012 - 4/11/2012			
DWR Inspector	Bob Duffey			
Accompanied By	Tom Smythe Lake Co.			

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Lake County Watershed Protection District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Poge, Alley and Clover Creek Diversion	Right	1.53	04/11/2012 04/11/2012	Bob Duffey

LMR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.53	0.53	Earthen Levee	Vegetation	LS	A Ma	V1 : Control annual grass and weeds on the levee slopes and easements.	39.176415 ° -122.902685 °	39.176415 ° -122.902685 °	5 Y
DWR ID: DWR_NA0009_04_s_2012_5										
2	0.82	0.87	Earthen Levee	Encroachments	LS	M En	FE : Fences	° °	° °	3
DWR ID: DWR_NA0009_04_s_2012_3										
3	0.90	0.90	Earthen Levee	Encroachments	LS	C Ma	GA : Garbage	39.178545 ° -122.896648 °	39.178545 ° -122.896648 °	1
DWR ID: DWR_NA0009_04_s_2012_1										
4	1.05	1.18	Earthen Levee	Trim / Thin Trees	LS	M Ma	T1 : Trim trees to at least five feet above ground level.	39.180479 ° -122.896567 °	39.181947 ° -122.895112 °	2 Y
DWR ID: DWR_NA0009_04_s_2012_2										
5	1.19	1.19	Earthen Levee	Encroachments	LS	M En	PR : Prunings	39.182074 ° -122.895053 °	39.182074 ° -122.895053 °	8 Y
DWR ID: DWR_NA0009_04_s_2012_8										
6	1.19	1.26	Earthen Levee	Vegetation	LS	M Ma	V2 : Remove the wild growth other than native grasses from the levee slopes.	39.182154 ° -122.895005 °	39.182951 ° -122.894409 °	9
DWR ID: DWR_NA0009_04_s_2012_9										

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Lake County Watershed Protection District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Poge, Alley and Clover Creek Diversion	Right	1.53	04/11/2012 04/11/2012	Bob Duffey

Levee Mile Report Line	1
Start Levee Mile	0.53
End Levee Mile	0.53
Location	Land Side
Category	Earthen Levee
Item	Vegetation
View of the levee with grasses on both slopes.	
rduffey_s_20120416_587.jpg	



Levee Mile Report Line	4
Start Levee Mile	1.05
End Levee Mile	1.18
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Remove the trees and vegetation from the toe of the levee.	
rduffey_s_20120416_590.jpg	



Levee Mile Report Line	5
Start Levee Mile	1.19
End Levee Mile	1.19
Location	Land Side
Category	Earthen Levee
Item	Encroachments
View of the walnut tree prunings along the toe of the levee.	
rduffey_s_20120416_588.jpg	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2012 Levee Inspection Results

Lake County Watershed Protection District

Waterway	Bank	Unit Miles
Unit No. 05 Clover Creek and Clover Creek Diversion	Left	1.04

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/11/2012 - 4/11/2011			
DWR Inspector	Bob Duffey			
Accompanied By	Tom Smythe Lake Co.			

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Lake County Watershed Protection District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Clover Creek and Clover Creek Diversion	Left	1.04	04/11/2012 04/11/2011	Bob Duffey

LMIR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.30	0.30	Earthen Levee	Vegetation	LS	M Ma	V4 : Elderberries are blocking visibility and flood fight capability.	39.176957 ° -122.898673 °	39.176957 ° -122.898673 °	3 Y
DWR ID: DWR_NA0009_05_s_2012_3										
2	0.56	0.56	Earthen Levee	Vegetation	LS	A Ma	V1 : Control annual grass and weeds on the levee slopes and easements.	39.175710 ° -122.903032 °	39.175710 ° -122.903032 °	4 Y
DWR ID: DWR_NA0009_05_s_2012_4										

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Lake County Watershed Protection District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Clover Creek and Clover Creek Diversion	Left	1.04	04/11/2012 04/11/2011	Bob Duffey

Levee Mile Report Line	1
Start Levee Mile	0.30
End Levee Mile	0.30
Location	Land Side
Category	Earthen Levee
Item	Vegetation

View of the elderberries along the landside toe of the levee.

rduffey_s_20120312_367.jpg



Levee Mile Report Line	2
Start Levee Mile	0.56
End Levee Mile	0.56
Location	Land Side
Category	Earthen Levee
Item	Vegetation

View of the grasses on both slopes.

rduffey_s_20120416_594.jpg



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---